



### Record Filtering

Quickly display and report on the data needed at the moment.

### Non-Normal Data

If the measurement data has a single-sided tolerance, Buddy can optionally command Minitab to generate a Goodness-of-fit test and then use the highest P value when running non-normal charts.

### Prolink Charting - Charts

Create charts without the need for Minitab. These charts can be used automatically in Excel Jobs.



### Prolink Charting - Statistics

A myriad of statistical calculations are available via Prolink Charting allowing the creation of robust reports.

		Reference Value
37		4.495381
38		
39	Calculations	Min 4.491416
40		Max 4.506641
41		Average 4.499696
42		Range 0.015225
43		Cp 0.91864
44		Cpk 0.893453
45		

### Characteristic Filtering

Reduce on-screen clutter to quickly identify only the most critical characteristics.



Please download a 30-day trial version from our website and try it out!

Prolink Corporation • 860.659.5928 • www.prolinksoftware.com